





Technical Training News

Daikin Technical Training is pleased to announce the release of DVT-142 Blower Guard Kit Installation Video and a document explaining Blower Guard Kit Status Codes. Both supplement all 3 sets of instructions (IO-7012A, IO-7013A, and IO-7014A) for proper installation and operation of the Blower Guard Kits on the affected Daikin brand 90% condensing furnaces with a constant volume (variable speed ECM) motor outlined in Daikin Technical Services Bulletin [TSB-OT-0016](#).

To access the DVT-142 Blower Guard Kit Installation Video please click on the video or scan the code below.

For Daikin Technical Training assistance, please email TechnicalTraining@daikincomfort.com



To access the Blower Guard Kit Status Code Explained Document please click on the button below.

Blower Guard Kit Status Code Explained

Daikin North America LLC, 19001 Kermier Road, Waller, Texas 77484,
United States, 713.861.2500

[Unsubscribe](#) [Manage preferences](#)